KIT IS NO LONGER GOOD, ONLY D2741 AND D3488-042. IS GOOD B71956 0.00

\*110\* HandFinish

Hand Finishing

110

Memo

DISSASSEMLE TUBE

0.00

STRIP, REPOWDER COAT AND RE-ASSEMBLE

STRIP ENTIRE TUBE, D 3488-041 AND D2741

1x d 11/2/06/01

Page 1

Insp.

\*01010\*

Thursday, May	31, 2012 1:3	4:41 PM		**************************************	STA"							Page 2
·Item ID: Revision ID: Item Name:	D350-636-0 Skidtube STD	16 w/ Training Wearplates	s, RH	Accept	*N900	<b>040</b>	100	)*	Setup	Start Stop	*N:	S1* S2*
Start Date: Required Date: Reference:	5/23/2012 5/24/2012 RMA RA11	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item I Customer:		AR001				ı V.	
Approvals:	Process Pla		Date:	6		ate:	<del>.</del>		Run	Start Stop	*N  *N	R1* R2*
Sequence ID/ Work Center II 120 *170* QC Quality Control	D	Operation Description QC5- Inspect part comple Memo	eteness to step on W/O	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
*130 *130* HandFinish Hand Finishing		Chemical Conversion Co  Memo  Re-alodine to		0.00 0.00 n 4.1.2.1 do not acid etch.					*	<b>d</b>	H	12/06/06
140 <b>*14^*</b> QC Quality Control		QC3- Inspect Part Finish  Memo		0.00				<u>/</u>	- <i>J</i> J-	<u>/</u>		ML 12/06/66

Work Order ID 84818 Page 3 Thursday, May 31, 2012 1:34:41 PM Item ID: D350-636-016 Accept \*N900040100\* Setup Start **Revision ID:** Skidtube STD w/ Training Wearplates, RH Item Name: **Start Date:** 5/23/2012 Start Qty: 1.00 **Cust Item ID:** Req'd Qty: 1.00 Required Date: 5/24/2012 **Customer:** CU-DAR001 Reference: RMA RA111351 Run Start Process Plan: **Approvals:** Date: **Tooling:** Date: Stop QC: SPC (Y/N): Date: Date: Sequence ID/ Operation Tool ID Reject Set Up/ Tool # Plan Accept Reject Insp. **Work Center ID** Description **Run Hours** Code Qty Qty Number Stamp 150 White Gloss(Ref:4.3.5.1) per QSI005 4.3-Alum 0.00 \*150\* Powdercoat 0.00 Memo Powder Coating REPOWDER COAT TUBE, D2741 AND D3488-041 m121134 OVEN TEMPERATURE

160

QC3- Inspect Part Finish

0.00

\*160\*

QC

Memo

FINISH TIME:

0.00

Quality Control

1xpr & Il aloclor

Page 4

Thursday, May.	31, 2012 1:34	4:41 PM	,, ,	t 1	( ) ! ( )						0
Item ID: Revision ID:	D350-636-0	16		Accept	*N90	00040	110	<b>n</b> *	Setup Star	rt *N	S1*
Item Name:	Skidtube STD	w/ Training Wearplate	es, RH						Sto	<sup>p</sup> *N	<b>S2*</b>
Start Date: Required Date:	5/23/2012 5/24/2012	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Ite Custom		DAR001				( 12
Reference:	RMA RAII	1351									
Approvals:	Process Pla	n:	Date:	Tooling:		Date:	, a sa.	]	Run Stai	" \	R1*
	QC:		Date:	SPC (Y/N):		Date:			Sto	*N	R2*
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours 0.00	Tool I	D Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
*170* HandFinish Hand Finishing		<b>Memo</b> 1- Install in	iserts as per Dwg D4168	0.00				1 RH	X.	<b>3</b>	12/06/07
		1-Inspect fo	or Foreign Objects								
		2-Spray ins	ide of tube with "LPS-3	batch: N/A							
		per dwg D4 SIKA FLEX BATCH:	1168 K 241	vearshoes and ground hand	lling hardware as						
		4-assemble A/R 55-o'ri	o'ring to plug as per dwing lube batch:ilo 3	g D3492 and apply o'ring t	ube						
		5-Coat all e	exposed fasteners with "L	LPS Procyon" batch: 114	4596						
<sup>180</sup> *18∩*		QC5- Inspect part comp	leteness to step on W/O	0.00	2/06/07						
QC		Memo		0.00	Coalo						
Quality Control									1		

Pick kit

18/6/18

**Quality Control** 

Page 5 Thursday, May 31, 2012 1:34:41 PM 'Item ID: D350-636-016 Accept \*N900040100\* Setup Start **Revision ID:** Skidtube STD w/ Training Wearplates, RH Item Name: **Start Date:** 5/23/2012 Start Qty: 1.00 **Cust Item ID:** Required Date: 5/24/2012 Reg'd Qty: 1.00 **Customer:** CU-DAR001 Reference: RMA RA111351 Run Approvals: Date: **Tooling:** Date: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool# Plan Accept Reject Reject Insp. **Work Center ID** Description **Run Hours** Qty Code Qty Number Stamp 190 Identify as per dwg & Stock Location: 0.00 \*190\* Packaging 0.00 for MLS 12-6-19 (46002 Packaging ADD NEW PAPERWORK 200 QC21- Final Inspection - Work Order Release 0.00 \*200\* QC 0.00 Memo

12/6/22 9X) MLJ 12(06/21

#### **Picklist Print**

Thursday, May 31, 2012 1:34:39 PM

Work Order ID:

84818

Parent Item:

D350-636-016

Parent Item Name:

Skidtube STD w/ Training Wearplates, RH

Start Date: 5/23/2012

Required Date: 5/24/2012

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP rev:A 10.09.28 new issue DD verf:EC

121689

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
ALS4-1032-225 Insert		Purchased	No			<u>-</u> -	Each	819.0000	- #40 3 5° ° °	4	(P)	12/0	6/07
				Location		Loc Qty	L	oc Code				,	1
				ST281		796	_						
					8696	146							
					0768	62							
				11	8386	55							
					8966	68							
				12	1269 🟏	465							
				ST282		23							
					0410	10			-				
				12	0451	13							
AN3C34A BOLT		Purchased	No				Each	41.0000	. <del>.</del>	1	P)	12/0	6/07
				Location		Loc Qty	<u>L</u>	oc Code				·	l
				ST353		41							
					6075 🗸	21							
				11	7514	20							
AN3C36A BOLT	<b>\</b>	Purchased	No				Each	162.0000	, whicher o	4_6	D 12	106/6	7
				<b>Location</b>		Loc Oty	<u>L</u>	oc Code		$\sim$		ı	
				FG		4							
				10	1261	4							
				ST353		158							
				110	6590	0							
					9083	2							
					9324	23							
					1388	33							
				12	1389	50							

50

W/O:			WC	RK ORDER CHANG	ES				· · · · · · · · · · · · · · · · · · ·	
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			٠							
			· · · · · · · · · · · · · · · · · · ·		·					
			. 4							
Part No	:	PAR #:	Fault Cate	gory:	_ NCF	R: Yes I	No DQ	A:	_ Date: _	
	R	esolution:	Disposition	n: <u>'</u>	QA:	N/C Cid	sed:		Date:	
NCR:			WORK ORDI	R NON-CONFORM	ANCE	(NCR	)			
DATE	STEP	Description of NC	Initial	Corrective Action Sect Action Description						Approval
	1	Section A	Chief Eng	Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
			• • • • • • • • • • • • • • • • • • •							
·							£   			
					ļ					

Work Order ID:

84818

Parent Item:

AN3C37A

BOLT

D350-636-016

Parent Item Name:

Skidtube STD w/ Training Wearplates, RH

Purchased

**Start Date:** 5/23/2012

Required Qty: 1.00

Required Date: 5/24/2012

Start Qtv: 1.00

Location ST354

Loc Qty 116874 117010 120422 121068 121585

Loc Code 141 11 2 3 75 50 Each 32.0000

141.0000

Each

Purchased

No

No

Location Loc Qty ST354 32 106176 6 25

Loc Code

AN3C6A **BOLT** 

Purchased No Each 455.0000

Location	Loc Qty	Loc Code	
FP001	1		
111982	1		
ST351	454		
111982	2		
116419	23		
116549	2		
116704	12		
117619	10		
117688	i		
117872	5		
118422	13		
119449	21		
120423	3		
120693 🗸	162		
121682	200		

DuitA	ospace	LIU								
W/O:			V	ORK ORDER CHA	NGES					
DATE	STEP	PRO	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							`!			
Part No		PAR #:								
	R	esolution:	Disposit	ion: '	QA:	N/C Clos	sed:		Date: _	
NCR:			WORK OR	DER NON-CONFOR	RMANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial	Corrective Action Action Description	Section B	Sign &	Verific Section		Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng		Date				
	i i									
		,								
	A.									:
,										
1 1	1	1	1	1			1		1	i

Work Order ID: 84818 Parent Item: D350-636-016 **Start Date:** 5/23/2012 Required Date: 5/24/2012 Skidtube STD w/ Training Wearplates, RH Parent Item Name: Start Qty: 1.00 Required Qty: 1.00 AN6C44A Purchased No Each 90.0000 **BOLT** Location Loc Qty Loc Code FG 2 103964 2 ST343 88 121013 11 121167 17 121440 50 121689 10 -AN8C21A Purchased No Each 57.0000 SBOLT Location Loc Qty Loc Code ST343 57 118758 3 4 121275 50 AN8C35A Purchased No Each 69.0000 **BOLT** Location Loc Qty Loc Code FP002 68 115960 118286 🗸 17 121275 50 ST346 114442 0 115188 0 115960 NAS1149C0332R Purchased AN960C10L No Each 0.0000 4 P 12/06/07. washer 121569~

W/O:			WO	RK ORDER CHANGE	ES			
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				-				
<del> </del>								
					:			
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes 1	lo DQA:_	Date: _	
		esolution:						
NCR:		<i>,</i> 41	NCE (NCR)	)				
DATE	STEP	Description of NC	Corrective Action Section B Verifica					Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector
						(		
		<u> </u>						
								·
•								
4					1	1		

Work Order ID: 84818 Parent Item: D350-636-016 Start Date: 5/23/2012 **Required Date: 5/24/2012** Skidtube STD w/ Training Wearplates, RH Parent Item Name: Start Qty: 1.00 Required Otv: 1.00 D2745 Manufactured Each 130.0000 Bushing Location Loc Otv Loc Code FP 6 79518 6 FP001 124 69529 76142 83260 122 D3492-1 Manufactured No Each 265,0000 8 Plug Location Loc Oty Loc Code FP002 242 69531 8 74444 2 76235 4 83259 228 23 83098 23 D3492-3 Manufactured Each 175.0000 8 Plug Location Loc Oty Loc Code FP-A 175 81967 5 83099 48 83529 122 D3493-1 No Each Manufactured 27.0000 Washer Location Loc Qty Loc Code ST050 27 77573 82023 26

								•	
W/O:			WO	RK ORDER CHANGE	ES				
DATE	STEP	PRO	OCEDURE CHAI	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			, , , , , , , , , , , , , , , , , , ,						
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	<b>A</b> :	Date: _	
	Re	solution:	Disposition	: '	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCF	<b>R</b> )			
DATE	STEP	Description of NC	Initial	Corrective Action Section	on B Sign &	Verification Approval			Approval
		Section A	Chief Eng	Action Description Chief Eng	Date	Sect	ion C	Chief Eng	QC inspector
							-		
,									,
•									

Work Order ID:	84818										
Parent Item:	D350-636-016								Star	t Date: 5/23/2012	Required Date: 5/24/2012
Parent Item Name:	Skidtube STD w/ T	raining Wearplates,	RH							rt Qty: 1.00	Required Qty: 1.00
D350-636-016 Skidtube STD w/ Traini	ng Wearplates, RH	Manufactured	No ·					Each	1.0000		1
				Locatio	<u>on</u>	Loc	c Oty		Loc Code		THE THE STATE OF T
				FG			1				-
					62438 62903	. C.	0				11 12 No.17
					64953	153M	0				U 12,06.22
					66106	400	0				-
					81400		l				-
D3631-1 Washer		Manufactured	No					Each	355.0000		8 P 12/06/07
	44			4	_		0.			· · · · · · · · · · · · · · · · · ·	2/06/07
				Locatio	<u>on</u>	Loc	<u>Qty</u>		Loc Code		
				FG	81874		340				-
					83588		338				-
				ST072			15				-
					68062		2				-
				•	75548		13				-
D3873-1		Manufactured	No					Each	462.0000		7
Bushing						•				7	<sup>7</sup> DD 12/06/07
				Locatio	<u>n</u>	Loc	Qty		Loc Code		i i
				ST057			6				
					79561		6				-
				ST067			456				
					64760		1				_
					68247		4				-
					73829		19				
					73830 76791		2 410			-	-
					79560		20				
											-

	. Johass							
W/O:			V	ORK ORDER CHANGE	S			***
DATE	STEP	PR	OCEDURE CH	IANGE	Ву	Date (	Qty Approva Chief Eng Prod Mgr	Approvai
			-			!		
<del></del>			rith Section 1					
Part No	:	PAR #:	Fault Ca	tegory:	NCR: Yes	No <b>DQA</b> :	Date:	
	R	esolution:	Disposit	ion: '	QA: N/C Clo	osed:	Date:	
NCR:			WORK OR	DER NON-CONFORMA	NCE (NCR	)		
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	n B Sign & Date	Verificat Section		
				0.110.7 2.19				
								:

Work Order ID: 84818 Parent Item: D350-636-016 Start Date: 5/23/2012 Require Date: 5/24/2012 Skidtube STD w/ Training Wearplates, RH Parent Item Name: Start Qty: 1.00 Required Qty: 1.00 D4170-1 Manufactured No Each 95.0000 Bushing Location Loc Qty Loc Code LG 50 82222 50 LG001 45 5 40 D4171-1 Manufactured Each 22.0000 12/06/07 Bushing Location Loc Qty Loc Code ST104 22 77008 2 82385 20 MS21043-3 Purchased Each 1.557.0000 Nut Location Loc Qty Loc Code ₫. FG 72 1 60 103691 72 GA 14 120693 14 ST301 1471 118077 2 118614 51 118686 30 119758 20 121255 368 121708 1000

W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
							<u> </u>				
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	A:	Date:			
		esolution:									
NCR:		\	WORK ORE	DER NON-CONFORMA	NCE (NCF	R)					
DATE	STEP	Description of NC		Corrective Action Section		Verifi	cation	Approval	Approval		
UAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC inspector		
									ŧ		
<b>}</b>											

Work Order ID:

84818

Parent Item:

D350-636-016

Parent Item Name:

Skidtube STD w/ Training Wearplates, RH

MS21043-6

NUT

Purchased

No

Start Date: 5/23/2012

Required Date: 5/24/2012

Start Qty: 1.00

622.0000

Required Qty: 1.00

Each

**MS21083C8** NUT

Purchased

No

Each 82.0000

100 1406/07

Location	1	Loc Qty	Loc Code		
304	_	76			
	121185	30			
	121349	46			
FP002		i			
	115884	1			
ST303		4			
	115884	0		. 4	
	118077	1			
	119309	2			
	119638	1			
ST304		1			
	121524	1			

Work Order ID: Parent Item: Parent Item Name: MS21083C8 NUT NAS1149C0363R Washer NAS1149C0832R WASHER

NAS1149D0863J

WASHER

84818

D350-636-016

Skidtube STD w/ Training Wearplates, RH

Purchased

Purchased

Purchased

Purchased

No

No

No

ST298

118078

121556

Start Date: 5/23/2012

Start Qty: 1.00

Required Date: 5/24/2012

Required Qty: 1.00

Location	Loc Qty	Loc Code	
· 304	76		
121185	30		
: 121349	46		
FPC02	1		
115884	1		
ST303	4		
115884	0		**************************************
118077	1		
119309	2		
119638	1		
ST304	1		
121524	l		
,	Each	2,958.0000	~ 9 C
			9 (08) 12/06/07
Location	Loc Qty	Loc Code	
ST297	2958	<del></del>	
114742	2958		
	Each	258.0000	
	Lacii	238.0000	12/06/07
			(JU) - (L/U) T
<u>Location</u>	Loc Qty	Loc Code .	V
ST297	258		
114915	258		
	Each	251.0000	2
			12/0/1
Location	Loc Qty	Loc Code	

Each

82.0000

251 34

17 100

100

Work Order ID:	84818							
Parent Item:	D350-636-016					Start Da	ite: 5/23/2012	Required Date: 5/24/2012
Parent Item Name:	Skidtube STD w/ Training Wearplate	s, RH					ty: 1.00	Required Qty: 1.00
NAS1515H3L WASHER	Purchased	No			Each	150.0000	~ (	DD) 12/06/04
			Location	Loc Qty		Loc Code		
			FG	40				
			102472	40				-
			ST277	110				-
			118686	. 3				•
			119438	1				-
			120360	11				
			121243	2			-	
			121556	93				
<b>NAS1611-010</b> O-RING	Purchased	No	*		Each	188.0000	· · · · · · · · · · · · · · · · · · ·	8D) 2/06/0=
			Location	Loc Oty		Loc Code		ı
			FP001	188				
			110915	14				
			117460	8				
		4	118077	1		1		
			118612	3				
			119438	47				
			121259	2				
			121415	4				
			121584	59				
			121723 V	50				
<b>NAS1611-013</b> O-RING	Purchased	No			Each	369.0000		8 P 12/06/07
			Location	Loc Qty		Loc Code		
			FP001	369				
			116582	5				
			117291	2				
			117887	53				
			119623	36				
			121584	23				
			121825	200				
			121826	50				
Thursday, May 31, 2	2012 1:34:40 PM		Shop Pack	cet Print		···		Page 9

			0		′	, 6
	QTY -041	QTY -042	QTY -043	-044	PART NUMBER	DESCRIPTION
D	Х	l			D4168-041	350 SKIDTUBE ASSEMBLY, LH
		Х			D4168-042	350 SKIDTUBE ASSEMBLY, RH
	L		X		D4168-043	350 SKIDTUBE ASSEMBLY, LH
				Х	D4168-044	350 SKIDTUBE ASSEMBLY, RH
	_1_	1	1 1	1	D2739	WEB
	8	8	8	8	D2743	SPACER
	1	1	1	1	D2744	CAP
	8	8	8	8	D2745	BUSHING
	1		1		D3488-041	BLADE FITTING, LH
		11		1	D3488-042	BLADE FITTING, RH
	4	4	4	4	D3490-1	SPACER
	4	4			D3490-3	SPACER
			4	4	D3490-5	SPACER
	8	8	8	8	D3492-041	PLUG ASSEMBLY
	8	8			D3492-043	PLUG ASSEMBLY
			8	8	D3492-045	PLUG ASSEMBLY
	8	8	8	-8	D3631-1	WASHER
	7	7	7	7	D3873-1	BUSHING
	1	1	1	1	D4154-041	WEARPLATE ASSEMBLY
	. 1				D4168-1	SKIDTUBE WELDMENT, LH
c l		1			D4168-2	SKIDTUBE WELDMENT, RH
ļ			1		D4168-3	SKIDTUBE WELDMENT, LH
ļ				1	D4168-4	SKIDTUBE WELDMENT, RH
	4	4	4	4	D4170-1	SPACER
- 1	1	1	1	1	D4171-1	BUSHING
- 1						
١	4	4	4		ALS4-1032-225	INSERT
- 1	4	4	4		AN3C6A	BOLT
-	1	1	1		AN3C34A	BOLT
į	4	_4	4		AN3C36A	BOLT
L	4	4	4		AN6C44A	BOLT
Į	1	1	1	1	AN8C35A	BOLT
- [	9	9	9		AN960C10	WASHER (OR NAS1149CO363R)
- 1	-4	4	4	4	AN960C10L	WASHER (OR NAS1149CO332R)
Ļ	1	1	1		AN960C816L	WASHER (OR NAS1149CO832R)
3 F	5	5	5		MS21043-3	NUT
,	4	4	4		MS21043-6	NUT
L	1	1	1		MS21083C8	NUT
Ţ	4	4	4	4	NAS1515H3L	WASHER
- 1						

#### **GENERAL NOTES:**

8

MATERIAL: MAKE D4168-1/-2/-3/-4 FROM D2600-3 EXTRUSION (INITIAL LENGTH = 120.0).

MATERIAL: MAKE D4168-1/-2/-3/-4 FROM D2600-3 EXTRUSION (INITIAL LENGTH = 120.0).
FINISH:
CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 PRIOR TO INSTALLING D2739 WEB.
POWDER COAT WHITE (REF. 4.3.5.1) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT AS INDICATED TO 1.0 ABOVE SKIDTUBE CENTER-LINE PER DART 005 4.4 (OPTIONAL).
TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
UNITS: INCHES UNLESS OTHERWISE NOTED
BREAK SHARP EDGES: N/A
IDENTIFICATION: N/A
WEIGHT: D4168-041/-042/-043/-044 = 32.3 LBS
WFI D PER DART QSI 104

WEIGHT: D4168-041/-042/-043/-044 = 32.3 LBS
WELD PER DART 051 004
FINAL CONFIGURATION SHOULD HAVE THE FOLLOWING MINIMUM MECHANICAL PROPERTIES:
MINIMUM YIELD TENSILE STRENGTH = 35 KSI
MINIMUM UTIMATE TENSILE STRENGTH = 38 KSI
COAT ALL EXPOSED FASTENERS WITH LPS LABORATORIES "LPS PROCYON" AFTER FINAL ASSEMBLY, CLEAN EXCESS OFF POWDER COATING WITH MEX DEGREASER.
SPACER AND PLUG INSTALLED SAME AS SECTION AJ-AJ EXCEPT HORIZONTAL
SPACER AND PLUG INSTALLED SAME AS SECTION AP-AP EXCEPT HORIZONTAL

A NEW ISSUE SC 10.08.09 REV. DESCRIPTION BY DATE DESIGN SC DART AEROSPACE USA, INC. DRAWN PORT HADLOCK, WA DRAWING NO. CHECKED REV. A D4168 MFG. APPR. SHEET 1 OF 11 APPROVED TITLE SCALE 350 SKIDTUBE ASSEMBLY DE APPR. NTS DATE

10.08.09

COPYRIGHT © 2010 BY DART AEROSPACE USA, INC

5

3

D


В D4168-041 350 SKIDTUBE ASSEMBLY, LH D4168-042 350 SKIDTUBE ASSEMBLY, RH DESIGN DART AEROSPACE USA, INC. DRAWN DRAWING NO. D4168 CHECKED REV. A MFG. APPR. SHEET 2 OF 11 350 SKIDTUBE ASSEMBLY


COPYRIGHT © 2010 BY DART AEROSPACE USA, INC.


COPYRIGHT PROJECT OF COPYRIGHT OF COPYRI APPROVED DE APPR. DATE 10.08.09


D4168-043 350 SKIDTUBE ASSEMBLY, LH D4168-044 350 SKIDTUBE ASSEMBLY, RH


DESIGN	sc	DART AEROSPACE USA, IN	INC			
DRAWN	SC	PORT HADLOCK, WA				
CHECKED	,ap	DRAWING NO.	REV. A			
MFG. APPR.	11/1	☐ D4168 shee	ET 3 OF 1			
APPROVED	W	TITLE	SCALE			
DE APPR.	1-4	350 SKIDTUBE ASSEMBLY	NTS			
DATE 10.	08.09	COPYRIGHT © 2010 BY DART AEROSPACE USA, INC. THE DOCUMENT IS PRIVATE AND CONSIDERTIAL AND IS EXPLED ON THE EXPRESS CONCIDENT THE NOT TO BE USED FOR ARY PLAYED ON COMED OF COMMUNICATION DAYS OF PERSON WITH WITHOUT THE PRIVATE OF PRIVATE OF THE PROPERTY OF THE PROPERTY OF THE PRIVATE OF THE P				




















# RA 111351 D350-636-016 B75349

Received @ April 19th Dart, 2012 Inspected@ Dart April 29th, 2012 Customer: Mustang Helicopters Customer Contact: Jim Moore Shipped from: Blackfalds AB CANADA

#### Instructions for RA 111351 D350-636-016 B75349 CHG002

- Kit has been all used and all returned in zip-lock bag
- Paper work is opened therefore no longer any good
- Only D2741 Blade is savable in Kit
- Dissemble tube
- Strip tube complete
- Strip Blade Fitting D3488-042
- Strip Blade D2741
- Re alodine if necessary and re powder coat tube and D3488-042 & D2741
  - o Re powder coat as per QSI 005 Gloss White
- Re assemble as per drawing
- Re pick kit for packaging
- Needs new PAPER WORK and LABELS
- Needs new BATCH #
- All work done needs to be under new Work Order #

<u>Time Estimate</u> = 5 HOUR (Finishing & stores)

<u>Departments Required:</u> Finishing & Stores

<u>Pictures Attached</u> = YES

# THIS INSTRUCTION SHEET MUST BE ATTACHED TO THE RESTOCKING WORK ORDER AT ALL TIMES!!!!

